

OPERATIONAL IMMEDIATE

TOP SECRET

29 Apr 57 12 16z
29 Apr 57 12 16z

25X1A
25X1A

IN 17980

OPIM [REDACTED] CITE [REDACTED] FOUR ZERO SEVEN ONE

25X1A
25X1A

HBT-16

[REDACTED] DASH ONE SIX DASH [REDACTED] TWO NINE ONE [REDACTED] TWO FIVE ZULU

25X1A

REF [REDACTED] ONE SEVEN TWO SIX (COMMANDER'S REPORT)

25X1A
25X1A
25X1A
25X1A

1. [REDACTED] REPORT, MISSION ONE THREE SEVEN ONE, [REDACTED]
[REDACTED], FLOWN TW⁰ SEVEN APRIL FIVE SEVEN, [REDACTED] THREE FIVE
SIX.

25X1A

2. MISSION ONE THREE SEVEN WAS CONSIDERED ALFA TOTAL LOSS.
THE [REDACTED] DASH THREE TRANSPOSED THREE ZERO ZERO ZERO FT
(TOTAL SIX ZERO ZERO ZERO FT) OF WHICH ONLY TWO TWO SIX EXPOSURES
WERE GOOD, OR TOTAL OF SIX SEVEN EIGHT FEET. MALFUNCTIONS WAS
SHUTTER FAILURE CAUSED BY CUTOFF SWITCH STOPPING HOTEL. SIERRA.
OPERATION. CLOUD COVERAGE RENDERED THE TWO TWO SIX GOOD
EXPOSURES USELESS.

25X1A

3. THE [REDACTED] DASH FIVE STOPPED AFTER FOUR HOURS TWENTY
MINUTES OF FLIGHT WITH FOUR ONE ZERO FT OUT OF ALFA POSSIBLE
FIVE FOUR ZERO FT USED. CAUSE UNKNOWN.

25X1A

CFN [REDACTED] FT FT FT H. S. [REDACTED]

25X1A

FT FT UNKNOWN

Q

C24

TOP SECRET

L/c